

L P C F C O 5 5 C
(1) (8) (9)

324729

OBSERVATION REPORT - SITE INVENTORY NO. 03115904

(11) (18)

Cock

CO. - L.P.C.

Region # NDate 11/10/83

(20) (25)

Sanaging
(Location)1 Kincaid
(Responsible Party)Letter Sent (Yes or No) no
(26)Samples Taken: Yes () No (x) Time: From 11:45 A mGround Water () Surface () Other () To 11:50 A mWeather 66° sunny

Photos Taken: Yes () No (x) Interviewed _____

Inspector B L E
(27) (29)Previous Inspection 8-5-82 Previous Correspondence 10-19-82 Site Open: Yes () No (x)

OPERATIONAL STATUS: TYPE OF OPERATION:

Operating () Landfill (x) Storage ()

Temporarily Closed () Random Dump () Salvage ()

Closed No: Covered () Other () A.C.D. ()

Closed and Covered (x) Quantity Received Daily(1-6) 1

(30)

AUTHORIZATION:

E.P.A. Permit (x) 7210

Variance ()

21(e) ()

Board Order ()

~~Illegal~~ (5) ()

Apparent Non-

Compliance (5) (x)

IMPROVED

SAME

DETERIORATED

I S or D

31

(62)

GENERAL REMARKS: During a recent inspection at the CID facility, this inspector was informed that a new berm was constructed along the south end of this site in order to divert rainwater (runoff) to the south east corner. (The original berm was both too low and was eroding). Thus, while in the area a quick stop was made at this site to confirm this berm. The berm is constructed of clay and runs the majority of the south width of the site and is about 2-3 ft. high.

INTERVIEW:

DIAGRAM:

